



SHAMROCK Natural Pozzolan™ / ASTM CLASS N

Information Contact Number
Tel 801 764-0999
Fax 801 764-0330

Emergency Phone Number
801 764-0999

Created 2/22/2005, Last Update 7/31/06

Section 1 - MATERIAL IDENTIFICATION AND INFORMATION

Chemical Composition: Pozzolan Type N - SiO₂, Al₂O₃, Fe₂O₃
Chemical Additives - N/A

Section 2 - PHYSICAL / CHEMICAL CHARACTERISTICS

Boiling point:	N/A	Specific gravity (H₂O = 1):	2.2-2.8
Vapor pressure (mmHg and Temp):	N/A	Melting point:	>2000° F
Vapor density (Air = 1):	N/A	Evaporation rate:	N/A
Solubility in water:	Negligible	Water reactive:	Not Reactive
Appearance and odor:	Off-white color, no odor. Average Particle size is 10-20 microns.		

Section 3 - FIRE AND EXPLOSION HAZARD DATA

Extinguisher media:	No special media.	Auto Ignition Temperature:	N/A
Flammability limits in air (%):	Not flammable.	LEL:	N/A
Special fire fighting procedures:	No special procedure:	UEL:	N/A
Water reactive:	N/A		
Unusual fire and explosion hazards:	None. This material is considered non-flammable and non-combustible Use fire extinguishing agent suitable for surrounding media.		

Section 4 - REACTIVITY HAZARD DATA

Stability:	Considered to be stable.
Hazardous decomposition products:	Decomposition products are unknown and not suspected.
Hazardous polymerization:	Hazardous polymerization not known to occur.
Conditions to avoid:	None.
Reactivity:	Material is considered inert. Avoid contact with strong acids, reducing agents, and oxidizers.

Section 5 - HEALTH HAZARD DATA

PRIMARY ROUTES OF ENTRY:

Ingestion:
Possible, but very unlikely to occur in sufficient quantities

Inhalation:

Can irritate respiratory tract; long term exposure to respirable silica above the OEL may produce silicosis in susceptible persons.

Skin and eye contact:
Can dry and irritate the skin; is not absorbed by skin. Can irritate eyes.

Hazardous:
Is not considered hazardous.

CARCINOGEN LISTED IN:

NTP: Yes (Crystalline Silica)*

IARC Monograph: Yes (Crystalline Silica)*

OSHA: No

Natural Pozzolan is not a listed carcinogen. Respirable crystalline silica from occupational sources is listed as carcinogenic to humans by IARC. NTP listed silica, crystalline (respirable) as a compound that may reasonably be anticipated to be a carcinogen. Presence of crystalline silica in respirable dust has not been established in this source.

Section 5 - HEALTH HAZARD DATA CONTINUED

Acute:

May cause irritation to the respiratory tract, eyes, or skin. Alkaline material; irritation may be aggravated by the addition of moisture (sweat).

Chronic:

Prolonged inhalation exposure may cause pulmonary fibrosis or chronic bronchitis

Signs and symptoms of exposure:

Irritation of eyes, skin and respiratory system.

Medical conditions generally aggravated by exposure:

May aggravate existing pulmonary condition if high dust situation is created. Dusting conditions should not occur under normal conditions.

EMERGENCY FIRST AID PROCEDURES:

Eye contact:

Flush for 15 minutes with water. Seek medical care as needed to remove particles and treat scratched cornea

Skin contact:

Wash with mild soap and water.

Inhalation:

Remove to fresh air; seek medical attention if respiratory symptoms (coughing, chest tightness, shortness of breath) persist

Ingestion:

Rinse mouth out with water. Induce vomiting if significant quantities are ingested

Section 6 - CONTROL AND PROTECTIVE MEASURES

Respiratory protection:

If airborne dust exposure approaches irritant levels, use half-mask or full-face air purifying respirator equipped with NIOSH or MSHA-approved high efficiency filters for protection against pneumoconiosis-producing dust. An airline respirator may be required where dust levels are extremely high. Recommend use of a NIOSH or MSHA-approved mask or respirator for nuisance dusts whenever dust is created.

Protective gloves:

Limit contact with skin. Use rubber or cloth gloves as necessary.

Eye protection:

Wear goggles or face shield as appropriate. Avoid contact lenses.

Ventilation to be used:

Keep dust levels low. Use general and local exhaust ventilation and dust collection systems to keep dust levels within acceptable limits.

Other protective clothing and equipment:

Protective clothing may be necessary under heavy dusting conditions.

Hygienic work practices:

Do not allow dust to get into eyes, to be inhaled, to be swallowed, or to remain on skin if irritation occurs. Minimize dusting. Practice good personal hygiene. Wash or shower after use. Launder clothing as normal.

Section 7 - PRECAUTIONS FOR SAFE HANDLING / LEAK PROCEDURES

Steps to be taken if material is spilled or released:

Do not create unnecessary airborne dust. Avoid inhalation. Use water mist to reduce dust. Provide ventilation as appropriate. Use personal protection; respiratory, skin and eyes.

Waste disposal methods:

Not classified as a RCRA hazardous waste. Material can be disposed of as inert solid in a permitted landfill. Follow applicable federal, state and local rules.

Precautions to be taken in handling and storage:

Avoid dust inhalation. Use water and other available means to minimize dusting. Use personal protection. Follow good housekeeping and personal hygiene practices.

Other precautions and/or special hazards:

Certain conditions (e.g. work in enclosed areas) could create over-exposure to trace elements. These activities should be evaluated for compliance with applicable standards.

This MSDS has been prepared in accordance with the Hazard Communication Rule 29 CFR 1910.1200. Information herein is based on data considered to be accurate as of the date prepared. No warranty or representation, express or implied, is made as to the accuracy or completeness of this data and safety information. No responsibility can be assumed by Shamrock Pozzolan LLC, or its partners and vendors for any damage or injury resulting from abnormal use, failure to adhere to recommended practices, or from any hazards inherent in the nature of the product.

